

Strain sensor X-106 for dynamic applications with integrated amplifier and digital zero adjustment


Models

X-106

Very small and compact
design



70 x 25 x 17 mm, 4x M6,
0...50 $\mu\text{m/m}$, 0...100 $\mu\text{m/m}$, 0...250 $\mu\text{m/m}$, 0...360 $\mu\text{m/m}$, 0...500 $\mu\text{m/m}$



Features

- Analogue signal path with fast response time
- For dynamic applications with external input for automatic zero point adjustments, qualified for periodical and recurring zero point adjustment
- Zero point adjustment is stored after power-off, no limitations on zero point adjustments
- With integrated amplifier with $\pm 10\text{ V}$ or 4-20 mA

Application

Dynamic applications describe recurring, fast measurement cycles, as usually found in presses. In cyclic applications, it is important that the zero point is tared in regular intervals in order to minimize drifting of the measuring signal. Thanks to the digital input, the zero point adjustment can be easily taught-in by the PLC.

The strain sensors can be used for the following applications:

- Indirect force measurement by detecting smallest strains allows efficient control of relevant process parameters (e.g., presses, assembly machines, welding machines, jigs, feed force)
- Limit value monitoring to avoid overloads
- Monitoring and documentation of process forces for increased process reliability (eg joining forces, assembly machines, pressing force, detection of tool breakage and wear)

The zero point adjustment at these strain sensors is carried out by a digital zero adjustment mechanism. The zero point adjustment is stored permanently, it is not lost after a power off. It provides a non-volatile, stable zero point independent of cycle times. Therefore, it is qualified for all dynamic applications and can be used in all kind applications which require a periodical zero point reset, triggered by a digital input.

Connection / Force type	Measuring range	0-10 V	4-20 mA	4-12-20 mA (Zero at 12 mA)
X-106 with M12-connector				
Signal positive on tension	0...50 µm/m	X-106-80-M12-1-50Z	X-106-81-M12-1-50Z	X-106-84-M12-1-50Z
	0...100 µm/m	X-106-80-M12-1-100Z	X-106-81-M12-1-100Z	X-106-84-M12-1-100Z
	0...250 µm/m	X-106-80-M12-1-250Z	X-106-81-M12-1-250Z	X-106-84-M12-1-250Z
	0...360 µm/m	X-106-80-M12-1-360Z	X-106-81-M12-1-360Z	X-106-84-M12-1-360Z
	0...500 µm/m	X-106-80-M12-1-500Z	X-106-81-M12-1-500Z	X-106-84-M12-1-500Z
Signal positive on compression	0...50 µm/m	X-106-80-M12-1-50D	X-106-81-M12-1-50D	X-106-84-M12-1-50D
	0...100 µm/m	X-106-80-M12-1-100D	X-106-81-M12-1-100D	X-106-84-M12-1-100D
	0...250 µm/m	X-106-80-M12-1-250D	X-106-81-M12-1-250D	X-106-84-M12-1-250D
	0...360 µm/m	X-106-80-M12-1-360D	X-106-81-M12-1-360D	X-106-84-M12-1-360D
	0...500 µm/m	X-106-80-M12-1-500D	X-106-81-M12-1-500D	X-106-84-M12-1-500D

Strain sensor X-106-8

70 x 25 x 17 mm, 4x M6,

Up to 500 µm/m



Specifications

Performance

Measuring range	0...50 µm/m 0...100 µm/m 0...250 µm/m 0...360 µm/m 0...500 µm/m
Linearity	< 0.3 % from full-scale
Hysteresis	< 0.3 % from full-scale
Repeatability of reinstallation	Typ. 1 %, max 2 %
Cut-off frequency	5000 Hz (-3dB)
Resolution	Analog signal path

Electrical data

Power supply	18...30 VDC, < 50 mA
Output signal at full scale	± 10 V / 4-20 mA / 4-12-20 mA
Output signal at overload	± 11.5 V / 1.5-23 mA

External zero reset

Measurement mode	< 3 V or open
Zero reset / adjustment	8...33 V
Minimal pulse duration	0.5 ms
Total duration zero reset	5 ms
Adjustment of zero point	200 % from full-scale
Max numbers of tarings	Unlimited

Materials

Housing	Steel (TC 11.1 ppm / °C)
Weight	100 gr


Mechanical data

Life endurance alternating 90 % load	10 ⁸ cycles
Electrical connection	M12 plug, 5 pole, male


Environmental data

Ambient temperature	-10...65 °C
EMV standards	IEC 61000-4-5, Performance A
Shock and vibration	EN60068-1-6/27
Protection rate	IP 64

Mechanical dimensions



Block diagram



Wiring

Pin assignment	X-106-8
PIN 1	Power +
PIN 2	Signal -
PIN 3	0V (GND)
PIN 4	Signal + (10 V / 4...20 mA / 4-12-20 mA)
PIN 5	Zero Reset

Ordering code

This strain sensor is delivered without mounting screws.

For detailed ordering information, please see page 2.

Zero reset / adjustment


The zero point adjustment at these strain sensors is carried out by a digital zero adjustment mechanism. The zero point adjustment is stored permanently, it is not lost after a power off. It provides a non-volatile, stable zero point independent of cycle times. Therefore, it is qualified for all dynamic applications and can be used in all kind applications which require a periodical zero point reset, triggered by a digital input.

The reset input does trigger a zero point adjustment by the PLC. It is available with an "Active Low" and "Active High" Logic.

The following parameters should be respected in regard to the external zero point adjustment:

External zero-point adjustment	"Active Low"	"Active High"
Measuring mode	8...33 or open	< 3 V or open
Zero point adjustment	< 3 V	8...33 V
Minimum pulse time	0.5 ms	0.5 ms

The following graph describes the characteristic during the zero point adjustment:



Mounting instructions

The strain sensors should be mounted on machined surfaces N9. The mounting thread should have a similar strength. Use the following parameter for tighten the socket screws:

	Screws	Tightening torque at strength class 10.9	Tightening torque at strength class 12.9
X-106	4x M6	14 Nm	18 Nm

Definition of accuracy

The accuracy includes the following parameters:

1. Linearity and hysteresis

The linearity and hysteresis specifies the measuring error in reference to the ideal BFSL curve. The maximum measuring error is stated in reference to the full scale value. This means that an accuracy of 0.5 % FS at a strain sensor with a measuring range of 0...250 $\mu\text{m/m}$ corresponds to a measuring error of only 1.25 $\mu\text{m/m}$.

2. Repeatability of reinstallation

The force closure between strain sensor and the structure it is applied to does vary slightly from installation to installation. As a consequence, the zero point and span is minimally moving from installation to installation. But the zero-point and the span can be easily recalibrated by the input for the zero-offset adjustment and by a recalibration with known process parameters. This eliminates a measuring error due to the reinstallation. In case that a recalibration is not possible in the application, the maximum error of reinstallation is specified within the data sheets.